

W-28

CHAIR

Hardware/Quincaillerie



A
X1

B
X2

C
X1


Tools Required/Outils requis




G*1
M10

H*1
M6

Components/Composantes



D
X1



E
X1



F
X2

